

Repaired and Improved

# Emergency Steam Turbine Revitalization

**ROBERT C. EISENMANN, SR.**  
SULZER TURBO SERVICES

An Australian refinery experienced the catastrophic failure of a steam turbine during a routine overspeed trip test. It was evident that severe rotor and casing damage had occurred. The refinery commissioned Sulzer Hickham, a Sulzer Turbo Services company, to carry out the emergency repair. Due to the extensive damage, the turbine and available spare parts were shipped to La Porte, TX (USA), where Sulzer Hickham put the turbine back into service in short time. Sulzer Hickham improved the original bearing design in order to enhance the operational behavior of the machine.




**1** Steam turbine blade and shroud failure. Sulzer Turbo Services repaired this steam turbine from an Australian refinery in just 10 days.

► This high-pressure turbine has a maximum continuous operating speed (MCOS) of 10,450 rpm and a desired overspeed trip point of 11,400 rpm. During a maintenance shutdown, the spare turbine rotor was installed. Following reassembly, the uncoupled turbine was ramped up to 10,000 rpm with no evidence of distress. According to established procedures, the governor was overridden mechanically to reach overspeed. During this operation, speed increased rapidly from 10,000 rpm to 15,400 rpm, and the turbine emitted a loud bang. The unit was shut down and disassembled for mechanical inspection, which revealed serious damage to casing, rotor, and blades (Fig. 1).

**2** The calculated rotor response of original and Flexure Pivot™ bearings shows reduced displacement with the new bearings.

Flexure Pivot™ is patented by KMC, and licensed by Bearings Plus Inc. Houston, TX



## Analysis of Rotor Dynamics

This turbine has a history of vibration problems. For the past 20 years, a tuned mass damper had been attached to the exhaust bearing housing to maintain peak-to-peak shaft vibration amplitudes between 50 and 75  $\mu\text{m}_{pp}$  (2.0 and 3.0 mil<sub>pp</sub>, 1 mil = 0.001 inch). Visual inspection revealed pressure dams in the top halves of both bearings, and the bottom bearing halves were purposely relieved of Babbitt. Obviously, the machine was susceptible to some type of instability, and the sleeve bearings had been modified to address this problem. Because of this observation, Sulzer Hickham developed an analytical rotor model and carried out a rotor dynamic analysis (RDA), which showed that it was necessary to modify the journal bearings.

The turbine was originally equipped with liner-type sleeve bearings, which are suitable for lower-speed machines, but which lack the rigidity and dimensional stability necessary for high-speed turbomachinery. The RDA revealed a marginal design of the original sleeve bearings. The first critical speed was calculated to be 5500 rpm, which is very close to one-half of operating speed. The second critical speed was calculated to be 11,500 rpm, which is only 10% above MCOS. Any degradation in bearing stiffness would move the second critical down into the operating-speed range (Fig. 2). The RDA clearly identified a 4-pad, tilting-pad bearing as the best bearing configuration. The size of the turbine bearing housings, however, did not allow for the installation of a traditional tilting-pad bearing with rocker arms. It

was therefore necessary to minimize the bearing outer diameter, which led to the choice of the Flexure Pivot™ design (Fig. 3).

## Improved Bearing Design

The Flexure Pivot bearing is a one-piece construction without any potential for assembly errors, wearing of parts, or flutter of unloaded pads. This configuration effectively suppressed the first critical speed response and increased the second critical to 13,500 rpm (29% separation margin). Synchronous vibration amplitudes were reduced, and stability was improved considerably. In addition, bearing loads at operating speed were reduced by 48% compared with the original bearings. Overall, the Flexure Pivot bearings provided a major improvement to the response of this 50-year-old turbine rotor.

Further examination of rotor behavior and potential bearing housing response was conducted by using the Flexure Pivot bearings. Within the parameters examined, there was no further justification for keeping the 20-year-old tuned mass damper. Sulzer Hickham recommended removing this mechanical device from the exhaust-end bearing housing.

## Mechanical Repairs

Because the failed rotor had sustained severe blade and shroud damage, using the previously operating rotor was the only short-term solution. The journals in this rotor were coated with tungsten carbide and ground to size. The shaft coupling fit and both seal areas were coated with Inconel 718 and then ground to size. The rotor was balanced, and the shaft sur-

